
Lane Plating Works Superfund Site



Community Meeting March 7, 2019

▶ Lane Plating Superfund Site

5322 Bonnie View Road in Dallas, TX.





EPA's Role

Implement the Superfund law which allows EPA to clean up contaminated sites.

▶ Goals

- Protect human health and the environment
- Involve communities in the process
- Return sites to productive use



EPA Actions

- ▶ 2016 TCEQ referred the site to EPA. EPA immediate response to remove surface wastes.
- ▶ 2018 EPA adds the Site to the National Priorities List to complete the long-term cleanup.
- ▶ 2019 EPA begins studies for long-term cleanup.

U.S. BRA Region 6



What EPA will study

Soils

- Contamination from metal plating operations.


Surface Water

Runoff from the Site into nearby creeks.

Groundwater

- Contamination can seep to groundwater and discharge to surface water.
- Groundwater is not used for drinking water around the Site.





Graphical Presentation of the Preliminary Human Health Conceptual Site Model

Priorities

- **▶** Ensure no current human exposure
 - Contact with site soils.
 - Contact with surface water.
 - Consumption of groundwater.
- Develop long-term cleanup plans
- **▶** Engage the community in the solutions
- **▶** Implement the cleanup



What is next?

- Install new groundwater wells and sample
 - Evaluate how contamination can move
- Collect additional soils data
 - Determine depth of soil contamination
 - Sample in areas of surface water runoff
- Collect Sediment and Surface Water Samples
 - Evaluate possible impact from surface water runoff



EPA CONTACTS

- ► Kenneth Shewmake Superfund RPM 214.665.3198, shewmake.Kenneth@epa.gov
- ► Edward Mekeel Community Involvement Coord., 214.665.2252, mekeel.edward@epa.gov
- www.epa.gov/superfund/lane-plating.gov



